

Product Safety Recall

HEAD Sport GmbH recalls

20.01.2026

HEAD ski boots

Article code	Model name		Production years		
606616	NEXT EDGE 85HT	Rental model	2016 2017		
607056	VECTOR EVO ST		2017		
607311	ADVANT EDGE 85 R	Rental model	2017		
607335	RAPTOR 50HT	Rental model junior	2017 2018		
607337	RAPTOR 40HT	Rental model junior	2017 2018		
608033 608032	VECTOR RS 130 VECTOR RS 130S No liner		2018		
608113	ADVANT EDGE 105		2018		
609060	VECTOR EVO ST		2019		
607121	ADVANT EDGE 95		2017		
601113	FORMULA RS 120		2021		
601150	FORMULA 120		2021		
602113	FORMULA RS 120 GW		2022		
602124	FORMULA 120 GW		2022		
602127	FORMULA 120		2022		

Product Safety Recall


HEAD Sport GmbH recalls

20.01.2026

HEAD ski boots

COMMENT IDENTIFIER LES MODÈLES

Le code article du modèle se compose de six chiffres et se trouve dans la zone du talon, à l'intérieur de la chaussure de ski gauche.



POURQUOI LE PRODUIT EST-IL DANGEREUX

Les semelles peuvent se fissurer lors d'une utilisation normale. Cela peut nuire à la stabilité de la chaussure de ski et augmenter le risque de blessure.

QUE FAIRE

- Le produit ne doit plus être utilisé

POUR LES CONSOMMATEURS

Les consommateurs concernés par ce rappel recevront gratuitement une paire de chaussures de ski équivalente.

Nous vous remercions de votre compréhension et vous prions de nous excuser pour la gêne occasionnée.

HEAD Switzerland AG

Rothusstrasse 17

6331 Hünenberg

+41 417670707

info@ch.head.com